

WHAT TO DO WITH A BLOCKED OR NOT FUNCTIONING SUNVISOR!

When picking up the helmet, the sun visor is unconsciously grabbed (see photo 1), because of this the sun visor shoots out of the side. (see photo 2)


photo 1

photo 2

This is very easy to remedy by pushing the side of the sun visor back in. (see photo 3)



Make sure that the rotating parts of the sun visor are down on both sides. (see photo 4)





ELECE MKX SP SUPERTEL IN TOOL SILE / bollard KM